



SUBCONTRACTOR REQUEST FOR INFORMATION

TO: GUSD

PROJECT: GUSD Fire Alarm Systems Upgrade

Date of Request: 05/05/2019

ATTN: Conrad Tedeschi

Requested By: Don Horsley

SUBJECT: Fire Alarm System, CO Detection

Discrepancy Pricing Request Clarification Suggestion

Response Required By: ASAP

Action Required By: ASAP

Specification Reference: 267200


Plan Reference: FA-2

Item 1:

The specified FSC-851 Quad Detectors will not annunciate the CO alarm separately. If the intent is to provide code compliant CO detection than the FCO-951 Smoke/CO detector would be the correct device. The currently specified Red Fire speakers and strobes should be changed to "ALERT" or plain (red is okay however white is available). The sequence of operations should also be amended to include action required for CO alarm.

Thank you.

Response PROVIDE FCO-951 DETECTORS WHERE (QD) IS SHOWN ON PLANS.
ALL NOTIFICATION DEVICES SHOU BE PLAIN WHITE WITH ALO LETTERING.

 on 6/5/19